


# Ned Marine services B.V.

**CONDITIONAL SURVEY REPORT**

**M.V. "NOVA CURA"**

**Bijela - Montenegro**

**July 2011**



**Perfection in Inspection**

# **Conditional Survey Report**

## **July 2011 Bijela - Montenegro**

**REPORT CONTENTS:**

<b>Page 1</b>	<b>:</b>	<b>Content of report</b>
<b>Page 2</b>	<b>:</b>	<b>General information / Copies of reports</b>
<b>Page 3</b>	<b>:</b>	<b>Inspector / Contact details</b>
<b>Page 4</b>	<b>:</b>	<b>General Particulars</b>
<b>Page 5</b>	<b>:</b>	<b>Agreement</b>
<b>Page 6 - 18</b>	<b>:</b>	<b>General view</b>




**Perfection for Protection**

---

Ned Marine Services B.V. Tinststraat 109 2984 AN Ridderkerk The Netherlands  
Tel: +31 (0) 180 420 055 ---Fax: +31 (0) 180 499 810---E-mail: [info@nedmarine.com](mailto:info@nedmarine.com) ---  
<http://www.nedmarine.com>

---



## **Perfection in Inspection**

### **General Information**

**Name Vessel:**

**m.v. "NOVA CURA"**

<b>Type of Inspection</b>	<b>:</b>	<b>Conditional Survey Inspection</b>
<b>Requested By</b>	<b>:</b>	<b>Luykx Ultrasound BV Mr. Kees Luykx</b>
<b>Date (s) of Inspection</b>	<b>:</b>	<b>July 2011</b>
<b>Place of Inspection</b>	<b>:</b>	<b>Adriatic Shipyard Bijela - Montenegro</b>
<b>Inspection carried out in accordance with:</b>		<b>Owners request</b>
<b>Additional agreements for Inspection</b>	<b>:</b>	<b>Conditional Survey of Ultra Sonic Antifouling System</b>
<b>Circumstances of Inspection</b>	<b>:</b>	<b>Ship arrived in dry dock during dry weather and good circumstances.</b>
<b>Owner's representative present</b>	<b>:</b>	<b>Yes</b>
<b>Name owners representative</b>	<b>:</b>	<b>Mr. Marcel van Eenennaam</b>

### **copies of Report**


<b>Quantity of hard copies</b>	<b>:</b>	<b>Two (2 in agreement with Mr. K. Lukx)</b>
<b>Structure of Report</b>	<b>:</b>	<b>Conditional Survey inspection incl. actual photo's July 2011</b>
<b>Report contains following data</b>	<b>:</b>	<b>Actual photo's of Side shell and bottom plating including sea chests and USAF system.</b>

## **Perfection for Protection**

---

**Ned Marine Services B.V. Tinststraat 109 2984 AN Ridderkerk The Netherlands**  
**Tel: +31 (0) 180 420 055 ---Fax: +31 (0) 180 499 810---E-mail: [info@nedmarine.com](mailto:info@nedmarine.com) ---**  
**<http://www.nedmarine.com>**

---



## Perfection in Inspection

### Inspector details

**Name (s) of Inspector (s) :**

**Robin van Laar**  
**Technical Inspector**

### Contact details

**Name contact person :**

Ger Monster / Robin van Laar

**Function contact person :**

*Senior Technical Engineer / Technical Inspector*

**Company address :**

**Ned Marine Services BV**

Tinstraat 109

2984 AN Ridderkerk

The Netherlands

**Telephone, Fax and Mobile telephone number :**

Tel. +31 (0) 180 420 055

Fax. +31 (0) 180 499 810

Mob. +31 (0) 621 843 391

**E-Mail addresses :**

Direct E-mail. [g.monster@nedmarine.com](mailto:g.monster@nedmarine.com); [r.vanlaar@nedmarine.com](mailto:r.vanlaar@nedmarine.com)


General E-mail. [info@nedmarine.com](mailto:info@nedmarine.com)

## Perfection for Protection

---

**Ned Marine Services B.V. Tinstraat 109 2984 AN Ridderkerk The Netherlands**  
**Tel: +31 (0) 180 420 055 ---Fax: +31 (0) 180 499 810---E-mail: [info@nedmarine.com](mailto:info@nedmarine.com) ---**  
**<http://www.nedmarine.com>**

---



## Perfection in Inspection

### General Particulars

Vessels name	:	NOVA CURA
Type of Vessel	:	General Cargo Ship
Date of built	:	01 September 1999
Ship builder	:	Shipyard Severnav – Turnu Severin
Hull no.	:	168
Flag	:	Netherlands
Survey	:	Conditional survey - Overall Pre-inspection
Present Owner (s)	:	Nova Sea Transport
Vessel Manager	:	Nova Sea Transport
Vessel operator	:	Nova Sea Transport

### Main dimensions


Length (OA)	:	107.09 m
Breadth (MLD)	:	15 m
Depth (MLD)	:	7 m
Draught designed	:	6.16 m
GT/DWT	:	3.999/5.641 mt

## Perfection for Protection

---

Ned Marine Services B.V. Tinststraat 109 2984 AN Ridderkerk The Netherlands  
Tel: +31 (0) 180 420 055 ---Fax: +31 (0) 180 499 810---E-mail: [info@nedmarine.com](mailto:info@nedmarine.com) ---  
<http://www.nedmarine.com>

---



### **Perfection in Inspection**

**On request of owners of Luykx Ultrasound BV, Mr. K. Luykx, Ned Marine Services BV has been on board of the above mentioned vessel, for the performance of a inspection for the Ultra Sonic Anti Fouling System (USAF).**

**The ship "NOVA CURA" is sailing with the Luykx Ultrasound BV USAF system since 2009 to avoid re- in growth of shell and bottom plating including sea chests. The vessel is mainly trading in the Mediterranean sea.**

**After 2 years the system has proved that it keeps the vessel clean and free of barnacles, mussels, bars etc.**

**Before started a minutes of meeting has been held, with present Ship owners representative: Mr. M. Van Eenennaam who is sailing with this ship since 2009 and he found out that fuel consumption was improving and during a visual inspection in 2010 by his self that the vessel was clean and free of sea organism at that time.**

**Ned Marine Services BV has performed an inspection and this report contains information received during our inspection when the ship "NOVA CURA " just arrived at dry dock and before jobs were started during dry dock at Bijela – Montenegro end of July 2011.**


### **Perfection for Protection**

---

**Ned Marine Services B.V. Tinststraat 109 2984 AN Ridderkerk The Netherlands**  
**Tel: +31 (0) 180 420 055 ---Fax: +31 (0) 180 499 810---E-mail: [info@nedmarine.com](mailto:info@nedmarine.com) ---**  
**<http://www.nedmarine.com>**

---






**Perfection in Inspection**







Description	Photo 1	Photo 2	Remarks
<b>Photo 1</b> <b>Over all view</b>  <b>Photo 2</b> <b>Over all view</b>			<b>No growth of sea organism has been found.</b>
<b>Photo 1</b> <b>Over all view</b>  <b>Photo 2</b> <b>Over all view</b>			<b>No growth of sea organism has been found.</b>
<b>Photo 1</b> <b>Over all view</b>  <b>Photo 2</b> <b>Over all view</b>			<b>No growth of sea organism has been found.</b>
<b>General information</b>	<b>During visual inspection vessel just arrived in dry dock.</b> <b>Vessel's hull clean and free of marine growth.</b>		

**Perfection for Protection**

Ned Marine Services B.V. Tinststraat 109 2984 AN Ridderkerk The Netherlands  
 Tel: +31 (0) 180 420 055 ---Fax: +31 (0) 180 499 810---E-mail: [info@nedmarine.com](mailto:info@nedmarine.com) ---  
<http://www.nedmarine.com>




**Perfection in Inspection**

Description	Photo 1	Photo 2	Remarks
<b>Photo 1</b> <b>Over all view</b>  <b>Photo 2</b> <b>Over all view</b>			<b>No growth of sea organism has been found.</b>
<b>Photo 1</b> <b>Over all view</b>  <b>Photo 2</b> <b>Over all view</b>			<b>No growth of sea organism has been found.</b>
<b>Photo 1</b> <b>Over all view</b>  <b>Photo 2</b> <b>Over all view</b>			<b>No growth of sea organism has been found.</b>
<b>General information</b>	<b>During visual inspection vessel just arrived in dry dock.</b> <b>Vessel's hull clean and free of marine growth.</b>		

**Perfection for Protection**

Ned Marine Services B.V. Tinststraat 109 2984 AN Ridderkerk The Netherlands  
 Tel: +31 (0) 180 420 055 ---Fax: +31 (0) 180 499 810---E-mail: [info@nedmarine.com](mailto:info@nedmarine.com) ---  
<http://www.nedmarine.com>






### Perfection in Inspection







Description	Photo 1	Photo 2	Remarks
<b>Photo 1</b> <b>Over all view</b>  <b>Photo 2</b> <b>Over all view</b>			<b>No growth of sea organism has been found.</b>
<b>Photo 1</b> <b>Over all view</b>  <b>Photo 2</b> <b>Over all view</b>			<b>No growth of sea organism has been found.</b>
<b>Photo 1</b> <b>Over all view</b>  <b>Photo 2</b> <b>Over all view</b>			<b>No growth of sea organism has been found.</b>
<b>General information</b>	<b>During visual inspection vessel just arrived in dry dock.</b> <b>Vessel's hull clean and free of marine growth.</b>		

### Perfection for Protection

Ned Marine Services B.V. Tinststraat 109 2984 AN Ridderkerk The Netherlands  
 Tel: +31 (0) 180 420 055 ---Fax: +31 (0) 180 499 810---E-mail: [info@nedmarine.com](mailto:info@nedmarine.com) ---  
<http://www.nedmarine.com>




### Perfection in Inspection







Description	Photo 1	Photo 2	Remarks
<b>Photo 1</b> <b>Over all view</b>  <b>Photo 2</b> <b>Over all view</b>			<b>No growth of sea organism has been found.</b>
<b>Photo 1</b> <b>Over all view</b>  <b>Photo 2</b> <b>Over all view</b>			<b>No growth of sea organism has been found.</b>
<b>Photo 1</b> <b>Over all view</b>  <b>Photo 2</b> <b>Over all view</b>			<b>No growth of sea organism has been found.</b>
<b>General information</b>	<b>During visual inspection vessel just arrived in dry dock.</b> <b>Vessel's hull clean and free of marine growth.</b>		

### Perfection for Protection

Ned Marine Services B.V. Tinststraat 109 2984 AN Ridderkerk The Netherlands  
 Tel: +31 (0) 180 420 055 ---Fax: +31 (0) 180 499 810---E-mail: [info@nedmarine.com](mailto:info@nedmarine.com) ---  
<http://www.nedmarine.com>




### Perfection in Inspection






Description	Photo 1	Photo 2	Remarks
<b>Photo 1</b> <b>Over all view</b>  <b>Photo 2</b> <b>Over all view</b>			<b>No growth of sea organism has been found.</b>
<b>Photo 1</b> <b>Over all view</b>  <b>Photo 2</b> <b>Over all view</b>			<b>No growth of sea organism has been found.</b>
<b>Photo 1</b> <b>Over all view</b>  <b>Photo 2</b> <b>Over all view</b>			<b>No growth of sea organism has been found.</b>
<b>General information</b>	<b>During visual inspection vessel just arrived in dry dock.</b> <b>Vessel's hull clean and free of marine growth.</b>		

### Perfection for Protection

Ned Marine Services B.V. Tinststraat 109 2984 AN Ridderkerk The Netherlands  
 Tel: +31 (0) 180 420 055 ---Fax: +31 (0) 180 499 810---E-mail: [info@nedmarine.com](mailto:info@nedmarine.com) ---  
<http://www.nedmarine.com>




### Perfection in Inspection

Description	Photo 1	Photo 2	Remarks
<b>Photo 1</b> <b>Over all view</b>  <b>Photo 2</b> <b>Over all view</b>			<b>No growth of sea organism has been found.</b>
<b>Photo 1</b> <b>Over all view</b>  <b>Photo 2</b> <b>Over all view</b>			<b>After switching of the system inside sea chest for 2 month, minor smallpox has been found.</b>
<b>Photo 1</b> <b>Over all view</b>  <b>Photo 2</b> <b>Over all view</b>			<b>After switching of the system inside sea chest for 2 month, minor smallpox has been found.</b>
<b>General information</b>	<b>During visual inspection vessel just arrived in dry dock.</b> <b>Vessel's hull clean and free of marine growth.</b>		

### Perfection for Protection

Ned Marine Services B.V. Tinststraat 109 2984 AN Ridderkerk The Netherlands  
 Tel: +31 (0) 180 420 055 ---Fax: +31 (0) 180 499 810---E-mail: [info@nedmarine.com](mailto:info@nedmarine.com) ---  
<http://www.nedmarine.com>









**Perfection in Inspection**

Description	Photo 1	Photo 2	Remarks
<b>Photo 1</b> <b>Over all view</b>  <b>Photo 2</b> <b>Over all view</b>			<b>After switching of the system inside sea chest for 2 month, minor smallpox has been found.</b>
<b>Photo 1</b> <b>Over all view</b>  <b>Photo 2</b> <b>Over all view</b>			<b>No growth of sea organism has been found.</b>
<b>Photo 1</b> <b>Over all view</b>  <b>Photo 2</b> <b>Over all view</b>			<b>No growth of sea organism has been found.</b>
<b>General information</b>	<b>During visual inspection vessel just arrived in dry dock.  Vessel's hull clean and free of marine growth.</b>		

**Perfection for Protection**

Ned Marine Services B.V. Tinststraat 109 2984 AN Ridderkerk The Netherlands  
Tel: +31 (0) 180 420 055 ---Fax: +31 (0) 180 499 810---E-mail: [info@nedmarine.com](mailto:info@nedmarine.com) ---  
<http://www.nedmarine.com>


**Perfection in Inspection**

Description	Photo 1	Photo 2	Remarks
Photo 1 Over all view  Photo 2 Over all view			After switching of the system inside sea chest for 2 month, minor smallpox has been found.
Photo 1 Over all view  Photo 2 Over all view			After switching of the system inside sea chest for 2 month, minor smallpox has been found.
Photo 1 Over all view  Photo 2 Over all view			No growth of sea organism has been found.
General information	During visual inspection vessel just arrived in dry dock. Vessel's hull clean and free of marine growth.		







**Perfection for Protection**

Ned Marine Services B.V. Tinststraat 109 2984 AN Ridderkerk The Netherlands  
Tel: +31 (0) 180 420 055 ---Fax: +31 (0) 180 499 810---E-mail: [info@nedmarine.com](mailto:info@nedmarine.com) ---  
<http://www.nedmarine.com>





**Perfection in Inspection**


Description	Photo 1	Photo 2	Remarks
<b>Photo 1</b> <b>Over all view</b>  <b>Photo 2</b> <b>Over all view</b>			<b>No growth of sea organism has been found.</b>
<b>Photo 1</b> <b>Over all view</b>  <b>Photo 2</b> <b>Over all view</b>			<b>No growth of sea organism has been found.</b>
<b>Photo 1</b> <b>Over all view</b>  <b>Photo 2</b> <b>Over all view</b>			<b>No growth of sea organism has been found.</b>
<b>General information</b>	<b>During visual inspection vessel just arrived in dry dock.  Vessel's hull clean and free of marine growth.</b>		

**Perfection for Protection**

Ned Marine Services B.V. Tinststraat 109 2984 AN Ridderkerk The Netherlands  
Tel: +31 (0) 180 420 055 ---Fax: +31 (0) 180 499 810---E-mail: [info@nedmarine.com](mailto:info@nedmarine.com) ---  
<http://www.nedmarine.com>









M.V. "NOVA CURA"



Conditional Survey Report


**Ned Marine**  
services B.V.

### Perfection in Inspection






Description	Photo 1	Photo 2	Remarks
<b>Photo 1</b> <b>Over all view</b>  <b>Photo 2</b> <b>Over all view</b>			<b>No growth of sea organism has been found.</b>
<b>Photo 1</b> <b>Over all view</b>  <b>Photo 2</b> <b>Over all view</b>			<b>No growth of sea organism has been found.</b>
<b>Photo 1</b> <b>Over all view</b>  <b>Photo 2</b> <b>Over all view</b>			<b>No growth of sea organism has been found.</b>
<b>General information</b>	<b>During visual inspection vessel just arrived in dry dock. Vessel's hull clean and free of marine growth.</b>		

### Perfection for Protection

Ned Marine Services B.V. Tinststraat 109 2984 AN Ridderkerk The Netherlands  
Tel: +31 (0) 180 420 055 ---Fax: +31 (0) 180 499 810---E-mail: [info@nedmarine.com](mailto:info@nedmarine.com) ---  
<http://www.nedmarine.com>




**Perfection in Inspection**







Description	Photo 1	Photo 2	Remarks
<b>Photo 1</b> <b>Over all view</b>  <b>Photo 2</b> <b>Over all view</b>			<b>No growth of sea organism has been found.</b>
<b>Photo 1</b> <b>Over all view</b>  <b>Photo 2</b> <b>Over all view</b>			<b>No growth of sea organism has been found.</b>
<b>Photo 1</b> <b>Over all view</b>  <b>Photo 2</b> <b>Over all view</b>			<b>No growth of sea organism has been found.</b>
<b>General information</b>	<b>During visual inspection vessel just arrived in dry dock.</b> <b>Vessel's hull clean and free of marine growth.</b>		

**Perfection for Protection**

Ned Marine Services B.V. Tinststraat 109 2984 AN Ridderkerk The Netherlands  
 Tel: +31 (0) 180 420 055 ---Fax: +31 (0) 180 499 810---E-mail: [info@nedmarine.com](mailto:info@nedmarine.com) ---  
<http://www.nedmarine.com>




**Perfection in Inspection**

Description	Photo 1	Photo 2	Remarks
<b>Photo 1</b> <b>Over all view</b>  <b>Photo 2</b> <b>Over all view</b>			<b>No growth of sea organism has been found.</b>
<b>Photo 1</b> <b>Over all view</b>  <b>Photo 2</b> <b>Over all view</b>			<b>No growth of sea organism has been found.</b>
<b>Photo 1</b> <b>Over all view</b>  <b>Photo 2</b> <b>Over all view</b>			<b>No growth of sea organism has been found.</b>
<b>General information</b>	<b>During visual inspection vessel just arrived in dry dock.  Vessel's hull clean and free of marine growth.</b>		

**Perfection for Protection**

Ned Marine Services B.V. Tinststraat 109 2984 AN Ridderkerk The Netherlands  
Tel: +31 (0) 180 420 055 ---Fax: +31 (0) 180 499 810---E-mail: [info@nedmarine.com](mailto:info@nedmarine.com) ---  
<http://www.nedmarine.com>





**Perfection in Inspection**

Description	Photo 1	Photo 2	Remarks
<b>Photo 1</b> <b>Over all view</b>  <b>Photo 2</b> <b>Over all view</b>			<b>No growth of sea organism has been found.</b>
<b>Photo 1</b> <b>Over all view</b>  <b>Photo 2</b> <b>Over all view</b>			<b>No growth of sea organism has been found.</b>
<b>Photo 1</b> <b>Over all view</b>  <b>Photo 2</b> <b>Over all view</b>			<b>No growth of sea organism has been found.</b>
<b>General information</b>	<b>During visual inspection vessel just arrived in dry dock.</b> <b>Vessel's hull clean and free of marine growth.</b>		

**Perfection for Protection**

Ned Marine Services B.V. Tinststraat 109 2984 AN Ridderkerk The Netherlands  
 Tel: +31 (0) 180 420 055 ---Fax: +31 (0) 180 499 810---E-mail: [info@nedmarine.com](mailto:info@nedmarine.com) ---  
<http://www.nedmarine.com>